

## Electronic Acknowledgement Receipt

<b>EFS ID:</b>	4983115
<b>Application Number:</b>	10743857
<b>International Application Number:</b>	
<b>Confirmation Number:</b>	9100
<b>Title of Invention:</b>	Methods and apparatus for a stent having an expandable web structure
<b>First Named Inventor/Applicant Name:</b>	Randolf Von Oepen
<b>Customer Number:</b>	57360
<b>Filer:</b>	Paul N. Taylor
<b>Filer Authorized By:</b>	
<b>Attorney Docket Number:</b>	17601.41a.1.1.1.3
<b>Receipt Date:</b>	17-MAR-2009
<b>Filing Date:</b>	22-DEC-2003
<b>Time Stamp:</b>	20:55:02
<b>Application Type:</b>	Utility under 35 USC 111(a)

### Payment information:

Submitted with Payment	no
------------------------	----

### File Listing:

Document Number	Document Description	File Name	File Size(Bytes)/ Message Digest	Multi Part /.zip	Pages (if appl.)
1	NPL Documents	09582318_20020814_OA.pdf	589523 d291a6506b78e3999382c798bc5d8355948a921	no	13

**Warnings:**

**Information:**

2	NPL Documents	09582318_20030307_NOA.pdf	399713 c013ed1605dc8bb37e6428f3dc1c0805c d85	no	6
<b>Warnings:</b>					
<b>Information:</b>					
3	NPL Documents	09582318_20030717_OA.pdf	28123 b619ba1e15ce03d86ac2be08089555ba c839	no	1
<b>Warnings:</b>					
<b>Information:</b>					
4	NPL Documents	09742144_20020924_OA.pdf	619967 ce0f9a3dc8fab279f0000b684f3d783cc3 7613	no	12
<b>Warnings:</b>					
<b>Information:</b>					
5	NPL Documents	09742144_20030514_OA.pdf	555274 7b03041ba626041ce091d35e1167b1a140 e843d	no	10
<b>Warnings:</b>					
<b>Information:</b>					
6	NPL Documents	09742144_20030829_NOA.pdf	548717 109d01cd8d4271e368ac95c02b5e1f64eb5 3010	no	7
<b>Warnings:</b>					
<b>Information:</b>					
7	NPL Documents	09742144_20040108_IN.pdf	54569 a08bd1301f172c589551800318f723065c f6c	no	1
<b>Warnings:</b>					
<b>Information:</b>					
8	NPL Documents	09916394_20040302_OA.pdf	248956 6645806d27720dc120884b73ba4c083b23 d5cd	no	9
<b>Warnings:</b>					
<b>Information:</b>					
9	NPL Documents	09916394_20031009_OA.pdf	203060 8b7a554e1535620985418804ba221d8738 a9d2f	no	7
<b>Warnings:</b>					
<b>Information:</b>					
10	NPL Documents	09916394_20030812_OA.pdf	146550 516f83bd1cd5548056708931a095c26b1f1 5c617	no	5
<b>Warnings:</b>					
<b>Information:</b>					

11	NPL Documents	10884613_20050330_OA.pdf	957987 31409b4db00afe90bda925a6c28ec253baf	no	15
<b>Warnings:</b>					
<b>Information:</b>					
12	NPL Documents	10884613_20051114_OA.pdf	335451 91296c7f52a18b6114eef2869ac662117a524a6	no	8
<b>Warnings:</b>					
<b>Information:</b>					
13	NPL Documents	09967789_20030917_OA.pdf	742463 bc3d3bda52f8bhe3144a2777b2d214babe3410f0	no	12
<b>Warnings:</b>					
<b>Information:</b>					
14	NPL Documents	09967789_20040217_NOA.pdf	416363 117a72b2563a315a117aaf79c12e08aebc103c	no	6
<b>Warnings:</b>					
<b>Information:</b>					
15	NPL Documents	09967789_20040610_IN.pdf	55775 a2f98248ba572b6a09c4e4c7a67bcb3f40a3	no	1
<b>Warnings:</b>					
<b>Information:</b>					
16	NPL Documents	10859636_20070601_OA.pdf	222828 67d36d78511e8dd4b659dcd5d104070b5cefd3af	no	6
<b>Warnings:</b>					
<b>Information:</b>					
17	NPL Documents	10859636_20071231_OA.pdf	259407 8f16a0ab0718f51b61d2246daaf103043ee87995	no	6
<b>Warnings:</b>					
<b>Information:</b>					
18	NPL Documents	10859636_20081001_NOA.pdf	254104 79611f5a6ef84ab3a8bca33a8b240e13105680f0	no	4
<b>Warnings:</b>					
<b>Information:</b>					
19	NPL Documents	10903013_20070315_OA.pdf	156813 33c9f1164b0e0ef02f02a829b34102de3ba7b3ee	no	4
<b>Warnings:</b>					
<b>Information:</b>					

20	NPL Documents	10903013_20071119_OA.pdf	170259 d55e34523008671d9980b0b153417f65c3d59b78a	no	5
<b>Warnings:</b>					
<b>Information:</b>					
21	NPL Documents	10903013_20080514_OA.pdf	629636 a746b5d46d245edf7c27f9f90bef0b31977ab0	no	14
<b>Warnings:</b>					
<b>Information:</b>					
22	NPL Documents	10903013_20090105_OA.pdf	251835 5e43c13103db4d9fa277e5e1708f5234dc9f9	no	7
<b>Warnings:</b>					
<b>Information:</b>					
23	NPL Documents	10903014_20070315_OA.pdf	158427 804f3f1af0d3078d95c24a9a9a0b1da3f55ee	no	4
<b>Warnings:</b>					
<b>Information:</b>					
24	NPL Documents	10903014_20071116_OA.pdf	170515 808d8fe4d629b3a682a08351421ba36059f35	no	5
<b>Warnings:</b>					
<b>Information:</b>					
25	NPL Documents	10903014_20080513_OA.pdf	626699 a75c77befab7c30d4c99966cdf378b7540bb05	no	14
<b>Warnings:</b>					
<b>Information:</b>					
26	NPL Documents	10903014_20090113_OA.pdf	239568 2a4dc61ee05a208c9c196c3758d9521a9ef97	no	7
<b>Warnings:</b>					
<b>Information:</b>					
27	NPL Documents	10903080_20070315_OA.pdf	158088 c30b9279161d21ca9802b8ee0667055204f7a05	no	4
<b>Warnings:</b>					
<b>Information:</b>					
28	NPL Documents	10903080_20071119_OA.pdf	170835 b3a2dc5305f8a27263a7a70e37af9a91a1b086d	no	5
<b>Warnings:</b>					
<b>Information:</b>					

29	NPL Documents	10903080_20080512_OA.pdf	617533 6d290fba098bc102d4513af910c15e5d754c20f	no	14
<b>Warnings:</b>					
<b>Information:</b>					
30	NPL Documents	10903080_20081230_OA.pdf	279106 6d657bbe6f6b95c78cadbd4b04805a17501a105	no	7
<b>Warnings:</b>					
<b>Information:</b>					
31	NPL Documents	10909117_20070822_OA.pdf	159383 eb168bc8f2bc87a790a89619acda181d5a3f798a	no	4
<b>Warnings:</b>					
<b>Information:</b>					
32	NPL Documents	10909117_20080512_OA.pdf	587775 7617536a510ba9d113bc02987214661de16c1e	no	13
<b>Warnings:</b>					
<b>Information:</b>					
33	NPL Documents	10909117_20081230_OA.pdf	236723 e2aadd68c12954c282078be1e08116b4c9f0f	no	6
<b>Warnings:</b>					
<b>Information:</b>					
34	NPL Documents	10909118_20070329_OA.pdf	158871 a314e91d47c0982d4c35851890a07a97563b8f8	no	4
<b>Warnings:</b>					
<b>Information:</b>					
35	NPL Documents	10909118_20071119_OA.pdf	170963 5ed2d2c5ad463755fb3d7d4791e3ced610a10da7	no	5
<b>Warnings:</b>					
<b>Information:</b>					
36	NPL Documents	10909118_20080512_OA.pdf	443570 bedf156c3873c616dbf0615e5ba17b5e3dfead67	no	11
<b>Warnings:</b>					
<b>Information:</b>					
37	NPL Documents	10909118_20090105_OA.pdf	252121 07124668078004b75eef1a169c7079721544a5	no	7
<b>Warnings:</b>					
<b>Information:</b>					

38	NPL Documents	10954948_20070315_OA.pdf	157705 b127d2749cd9194E134003FA037cd809 897	no	4
<b>Warnings:</b>					
<b>Information:</b>					
39	NPL Documents	10954948_20071116_OA.pdf	169874 989a1fae8cd91d27b767618d62efab1ed5c 4ed1	no	5
<b>Warnings:</b>					
<b>Information:</b>					
40	NPL Documents	10954948_20080515_OA.pdf	620313 7d1d2428ba519165c79684801c5c359d2c c3d5d	no	14
<b>Warnings:</b>					
<b>Information:</b>					
41	NPL Documents	10954948_20090113_OA.pdf	251608 abdd46c09d79c26745dbec161b8b6511 11578a	no	7
<b>Warnings:</b>					
<b>Information:</b>					
42	NPL Documents	10955425_20070315_OA.pdf	157533 d5272717cd13e98198a15af96aaf653cd d2	no	4
<b>Warnings:</b>					
<b>Information:</b>					
43	NPL Documents	10955425_20071116_OA.pdf	170772 76122e1cd11af26d86a5d4c6c561cccd2 49bd	no	5
<b>Warnings:</b>					
<b>Information:</b>					
44	NPL Documents	10955425_20080513_OA.PDF	634272 48700e42ccc028ffcc014bda2575cd66fb3 55a7	no	14
<b>Warnings:</b>					
<b>Information:</b>					
45	NPL Documents	10955425_20090113_OA.pdf	253945 b0680d848124d6d72a78b1f0096a5dc5b e291	no	7
<b>Warnings:</b>					
<b>Information:</b>					
46	NPL Documents	11313110_20080108_OA.pdf	548042 2bc240a8f72bbbc6a3b2503fa5624159 a8fb0b	no	15
<b>Warnings:</b>					
<b>Information:</b>					

47	NPL Documents	11313110_20080702_OA.pdf	478401 752670f3ca0b015bdc17acc365e581376c3 5ac	no	11
Warnings:					
Information:					
48	NPL Documents	11404450_20090204_OA.pdf	202242 7db66ab2c0b0807c59a0d18c5db18a5c5 ee230	no	6
Warnings:					
Information:					
49	NPL Documents	11601475_20080722_OA.pdf	253329 c142c581a651d102d8b2029c595d8ec1330 12ba8	no	7
Warnings:					
Information:					
50	NPL Documents	11601475_20090106_OA.pdf	281702 dec6f0f95a0727149c9b070e1911bf1a6b2b ee801	no	8
Warnings:					
Information:					
Total Files Size (in bytes):			16457288		
This Acknowledgement Receipt evidences receipt on the noted date by the USPTO of the indicated documents, characterized by the applicant, and including page counts, where applicable. It serves as evidence of receipt similar to a Post Card, as described in MPEP 503.					
<b><u>New Applications Under 35 U.S.C. 111</u></b> If a new application is being filed and the application includes the necessary components for a filing date (see 37 CFR 1.53(b)-(d) and MPEP 506), a Filing Receipt (37 CFR 1.54) will be issued in due course and the date shown on this Acknowledgement Receipt will establish the filing date of the application.					
<b><u>National Stage of an International Application under 35 U.S.C. 371</u></b> If a timely submission to enter the national stage of an international application is compliant with the conditions of 35 U.S.C. 371 and other applicable requirements a Form PCT/DO/EO/903 indicating acceptance of the application as a national stage submission under 35 U.S.C. 371 will be issued in addition to the Filing Receipt, in due course.					
<b><u>New International Application Filed with the USPTO as a Receiving Office</u></b> If a new international application is being filed and the international application includes the necessary components for an international filing date (see PCT Article 11 and MPEP 1810), a Notification of the International Application Number and of the International Filing Date (Form PCT/RO/105) will be issued in due course, subject to prescriptions concerning national security, and the date shown on this Acknowledgement Receipt will establish the international filing date of the application.					